


Having trouble viewing this email? [Click here](#)



Never Cut The Rebar!

It has recently come to our attention that some installers cut rebar to install direct burial loops. We were shocked to learn that this installation method is described in some of our competitors' installation instructions.

Cutting the concrete's skeleton is never advisable. We recently spoke with a Chief Building Inspector in Huntington Beach, who was adamantly against the idea of cutting the rebar, and suggested the installers and manufacturers who use and promote such installations could

Stand Off Test Now Available in The BD Loops Labs

How far away should you install a loop from the gate? Ever wonder how far a loop's detection range reaches beyond the loop? Or how the size of a loop effects its detection range?



BD Loops new Stand Off Test is here to answer all the pressing questions installers face about detection range.

View the Test Here: [BD Loops Stand Off Test.](#)

AFA Fencetech '10

The 48th Annual AFA Convention & Trade Exhibition



This month BD Loops will be displaying at Fencetech '10. **We will be in booth #1505**, stop by and say hello!

We will be unveiling our new 3/16" sealant tip that enables installers to seal a BD Loops Saw-Cut loop in one pass!

Fencetech/Decktech '10
February 17-19, 2010
Orlando, Florida

[Learn more about Fencetech '10 here!](#)

Up Coming Shows

be found liable for any damages to the driveway that may occur as a result of the weakened skeleton.

Did You Know?



BD Loops has joined the IPI. (International Parking Institute)

The IPI is the industry's leading association for parking and transportation professionals. For more than 50 years, the International Parking Institute has provided leadership, training and resources.

To learn more about the IPI please visit their website at parking.org



The IDA Expo 2010
Come see us in Booth #4035



The IPI Conference and Expo
Come see us in Booth #710!

Thank you for your time, please feel free to contact us with any questions or concerns.

Sincerely,

Brian Dickson
General Manager
BD Loops

P: 714-890-1604

BD Loops
F: 714-890-1603

E: bdloops@aol.com

[Forward email](#)



This email was sent to studiodickson@yahoo.com by bdloops@aol.com | [Update Profile/Email Address](#) | Instant removal with [SafeUnsubscribe™](#) | [Privacy Policy](#).

BD Loops | 5362 Bolsa Ave Unit C | Huntington Beach | CA | 92649